From: Miller, Garyg
To: Ruiz, Carlos ERD
Subject: San Jacinto CAP

Date: Thursday, March 31, 2016 3:45:00 PM
Attachments: SJWP Dive Report FINAL w MAP.pdf

Addendum 2 OMM Plan Camera Security System 02292016.pdf

San Jacinto Surveillance Protocol 03312016.pdf

Daily Report 011 2016-03-24.pdf
Daily Report 012 2016-03-25 (002).pdf
Daily Report 010 2016-03-23.pdf

image1.JPG

<u>Daily Report 009 2016-03-22.pdf</u> <u>Daily Report 007 2016-03-19.pdf</u>

## Carlos,

As we discussed, here is the dive report with the sonar images.

Also, the information on the camera monitoring system.

Also, plans & reports on the inspections and repairs in the eastern cell – more in next email.

Thanks,

Gary Miller
Remedial Project Manager
EPA Region 6 – Superfund Division (6SF-RA)
214-665-8318
miller.garyg@epa.gov

